

Standard Calibration Sources [rev: 3/07]

State of California – Division of Measurement Standards Metrology Laboratory:	
California Department of Food and Agriculture Division of Measurement Standards 6790 Florin Perkins Rd. Suite 100 Sacramento CA 95828 Phone: 916-229-3024 [WS, WL, WK, TM, PP, V, SW, MT, T]	NOTE: State Metrology Laboratory has a current National Institute of Standards and Technology (NIST) “Certificate of Measurement Traceability” under the NIST State Laboratory Program for State legal metrology laboratories.
Standard Calibration Sources for Service Agencies and Industry	
County Metrology Laboratories (satellite facilities):	
Fresno County Agricultural Commissioner/Weights & Measures 1730 S. Maple Avenue Fresno, CA 93702 Phone: 559-456-7510 [WS, TM]	Kern County Agricultural Commissioner/Weights & Measures 1116 E. California Ave. Bakersfield, CA 93307 Phone: 661-868-6254 [WS, WL, TM]
Merced County Agricultural Commissioner/Weights & Measures 2139 W. Wardrobe Ave. Merced, CA 95340 Phone: 209-385-7431 [WS, WL, TM]	San Bernardino County Agricultural Commissioner/Weights & Measures 777 E. Rialto Ave. San Bernardino, CA 92415 Phone: 909-387-2140 [TM]
San Diego County Agricultural Commissioner/Weights & Measures 5555 Overland Ave., Bldg. 3 San Diego, CA 92123 Phone: 858-694-2778 [TM]	Shasta County Agricultural Commissioner/Weights & Measures 3179 Bechelli Lane, Suite 210 Redding, CA 96002 Phone: 530-224-4949 [TM]
Stanislaus County Agricultural Commissioner/Weights & Measures 3800 Cornucopia Way, Suite B Modesto, CA 95358 Phone: 209-525-4730 [WS, WL, TM]	Sonoma County Agricultural Commissioner/Weights & Measures 133 Aviation Blvd. #110 Santa Rosa 95403 Phone: 707-565-2371 [TM]
NOTE: County facilities are state directed satellite metrology laboratories with the state metrology laboratory headquarters in Sacramento.	

Measurement Discipline (Weights and Measures Application):

25 & 50 pound cast block weights, Class F
 500 & 1000 pound cast block weights, Class F
 Other weights & weight kits
 Field "test measures" 5 gallon
 Portable bottom drain provers; 5 gallons to 1000 gallons
 Other Volume
 Digital/electronic & mechanical stop watches
 Measuring tapes and rulers
 Temperature
 Pressure
 Humidity
 AC and/or DC voltage, current, and/or Resistance
 Frequency
 Gage blocks, calipers, micrometers, height gages, and/or ring gages G

[Recognition Codes]

WS
 WL
 WK
 TM
 PP
 V
 SW
 MT
 T
 P
 H
 AC/DC
 F

General Service and Calibration Sources [rev: 3/07]¹ for calibration and measurement disciplines

States Metrology Laboratories ² :	
Oregon Dept. of Agriculture (NVLAP) Measurement Standards Division 635 Capitol St. NE Salem, OR 97301-2532 Phone: 503-986-4672 [WS, WL, WK, TM, PP, V, SW, MT, T]	Nevada Dept. of Agriculture (NIST) 2150 Frazer Sparks, NV 89431 Phone: 775-688-1166 [WS, WL, WK, TM, PP, V, SW, MT, T]
Arizona Dept. of Weights and Measures (NVLAP) 4425 West Olive Avenue, Suite 134 Glendale, AZ 85302 Phone: 602-255-5211 [WS, WL, WK, TM, PP, V, SW, MT, T]	NOTE: All State Metrology Laboratories must have a current National Institute of Standards and Technology (NIST) "Certificate of Measurement Traceability" or National Voluntary Laboratory Accreditation Program (NVLAP) accreditation.
Private Organizations ² :	
Heusser Neweigh (A2LA) 1717 Solano Way, #24 Concord, CA 94520 Phone: 800-672-1440 [WS, WL, WK, T]	Southern California Edison (NVLAP) Edison ESI. 7300 Fenwick Lane Westminster, CA 92683 Phone: 866-723-2257 [WS, WL, WK]
Rice Lake Weighing Systems (NVLAP) 230 West Coleman St. Rice Lake, WI 54868 Phone: 800-472-6703 [WS, WL, WK]	Troemner, Inc. (NVLAP) 201 Wolf Drive Thorofare, NJ 08086 Phone: 800-681-4448 [WS, WL, WK]
Quality Control Services (A2LA) 2340 S.E. 11 th Avenue Portland, OR 97214 Phone: 800-843-1237 [WS, WL, WK, T]	Primary Instruments Incorporated (A2LA) 9553 Vassar Avenue Chatsworth, CA. 91311 Phone: 818-993-4971 [AC/DC, F, T, P, H, G]

¹ This table is a partial list of calibration resources and it is not intended as an endorsement of the listed organizations or their services. Service agencies and industry need to verify that a listed source is currently providing a specific certification and meets the accreditation requirements.

² NVLAP directory listing: <http://ts.nist.gov/ts/htdocs/210/214/scopes/programs.htm>

A2LA directory listing: <http://www.a2la.org/dirsearch/search9.cfm>

State Certificate of Measurement Traceability listing: <http://ts.nist.gov/ts/htdocs/230/235/statelabcontact.htm>

Measurement Discipline (Weights and Measures Application):

25 & 50 pound cast block weights, Class F
 500 & 1000 pound cast block weights, Class F
 Other weights & weight kits
 Field "test measures" 5 gallon
 Portable bottom drain provers; 5 gallons to 1000 gallons
 Other Volume
 Digital/electronic & mechanical stop watches
 Measuring tapes and rulers
 Temperature
 Pressure
 Humidity
 AC and/or DC voltage, current, and/or Resistance
 Frequency
 Gage blocks, calipers, micrometers, height gages, and/or ring gages G

[Recognition Codes]

WS
 WL
 WK
 TM
 PP
 V
 SW
 MT
 T
 P
 H
 AC/DC
 F

**General Service and Calibration Sources [rev: 3/07]¹
for calibration and measurement disciplines**

General Test and Measuring Instruments:	
SIMCO Corp. (California) Chatsworth San Diego	(A2LA) Phone: 818-773-9750 Phone: 858-292-1090
Pressure Gauges & Gauge LOX Cleaning:	
Gauge Repair Service (A2LA) 365 Van Ness Way, Suite 507 Torrance, CA 90501 (Calibration only)	NTS 5320 W. 104 th St. Los Angeles, CA 90045 (Cleaning only)
AstroPak 12201 Pangborn Ave. Downy, CA 90241 (Cleaning only)	Phone: 310-212-0912 Phone: 800-559-3202 Phone: 800-743-5444

¹ This table is a partial list of calibration resources and it is not intended as an endorsement of the listed organizations or their services. Service agencies and industry need to verify that a listed source is currently providing a specific certification and meets the accreditation requirements.

Measurement Discipline (Weights and Measures Application):

25 & 50 pound cast block weights, Class F
500 & 1000 pound cast block weights, Class F
Other weights & weight kits
Field "test measures" 5 gallon
Portable bottom drain provers; 5 gallons to 1000 gallons
Other Volume
Digital/electronic & mechanical stop watches
Measuring tapes and rulers
Temperature
Pressure
Humidity
AC and/or DC voltage, current, and/or Resistance
Frequency
Gage blocks, calipers, micrometers, height gages, and/or ring gages G

[Recognition Codes]

WS
WL
WK
TM
PP
V
SW
MT
T
P
H
AC/DC
F